

Burning-Rubber

Port		Soldan
+ 12V	1	+ 12V
+ 5V	2	+ 5V
- 5V	3	Gnd
Blau	4	5V
Rot	5	Grün
Coin 1	6	Coin 2
-	7	-
API	8	2Sp. P1
-	9	-
1Sp Schuß	10	2Sp Schuß
1Sp Down	11	2Sp Down
1. Up	12	2. Up
1. links	13	2. links
1. rechts	14	2. rechts
Sp	15	
	16	Sp.
GND	17	
	18	

