

17.88

1a

**** F-1 DREAM ****

WIRING DIAGRAM

SOLDER SIDE

PARTS SIDE

GND	-----	1	-----	GND
GND	-----	2	-----	GND
+5V	-----	3	-----	+5V
+5V	-----	4	-----	+5V
-5V	-----	5	-----	-5V
+12V	-----	6	-----	+12V
		7		
COIN 2	-----	8	-----	COIN 1
COIN LOCK OUT 2	-----	9	-----	COIN LOCK OUT 1
SP(-)	-----	10	-----	SP(+)
		11		
VIDEO GREEN	-----	12	-----	VIDEO RED
VIDEO SYNC	-----	13	-----	VIDEO BLUE
SERVICE SW	-----	14	-----	VIDEO GND
		15		
COIN SW 2	-----	16	-----	COIN SW 1
START SW 2	-----	17	-----	START SW 1
2P UP	-----	18	-----	1P UP
2P DOWN	-----	19	-----	1P DOWN
2P LEFT	-----	20	-----	1P LEFT
2P RIGHT	-----	21	-----	1P RIGHT
2P PUSH 1	-----	22	-----	1P PUSH 1
2P PUSH 2	-----	23	-----	1P PUSH 2
		24		
		25		
		26		
GND	-----	27	-----	GND
GND	-----	28	-----	GND

