

82

Yan Cha Maru

KEA GUL YAN CHA MARU

<i>Solder</i>		<i>Parts</i>
PARTS SIDE		SOLDER SIDE
GND	1	GND
GND	2	GND
	3	
	4	COIN SWITCH A
2P LEFT	5	1P LEFT
2P RIGHT	6	1P RIGHT
2P SHOOT	7	1P SHOOT
1P START	8	2P START
COIN COUNTER	9	
CCMP SYNC	10	COIN B
+12V	11	+12V
+12V	12	+12V
(+)S.P	13	(-) S.P
2P JUMP	14	1P JUMP
GREEN	15	RED
	16	BLUE
2P DOWN	17	2P UP
1P DOWN	18	1P UP
COIN A	19	SERVICE SW
+5V	20	+5V
+5V	21	+5V
GND	22	GND