

KIKI KAIKAI
===== 86/12/19

WIRING DIAGRAM

SOLDER SIDE

GND	1
GND	2
+5V	3
+5V	4
-5V	5
+12V	6
N.C	7
N.C	8
N.C	9
SPEAKER(-)	10
(AUDIO)GND	11
GREEN	12
SYNC	13
SERVICE SW	14
TILT SW	15
COIN SW 2	16
START SW 2	17
2P UP	18
2P DOWN	19
2P LEFT	20
2P RIGHT	21
2P PUSH 1	22
2P PUSH 2	23
N.C	24
N.C	25
N.C	26
+5V	27
+5V	28

PARTS SIDE

GND
GND
+5V
+5V
N.C
N.C
N.C
COIN COUNTER 1
COIN LOCKOUT 1
SPEAKER(+)
AUDIO(+)
RED
BLUE
GND
TEST SW
COIN SW 1
START SW 1
1P UP
1P DOWN
1P LEFT
1P RIGHT
1P PUSH 1
1P PUSH 2
N.C
N.C
N.C
GND
GND

