Corrections for Rolling Thunder* Self-Test Label and Operators Manual

The self-test label installed in the Rolling Thunder game and the Operators Manual are incorrect. The most important correction is a change in the recommended setting for the timer value: it should be 150 seconds. We suggest that you make the corrections listed below on your self-test label and in the Rolling Thunder Operators Manual.

Self-Test Label:

Figure 1 Self-Test Screen—TIMER should be 150 SEC. Also DIP SW B should read 00101000.

Table 2 DIP Switch B Option Settings—Under Time Value, move the triangle to point to 150 seconds, to indicate that this is the manufacturer's recommended setting.

Operators Manual:

Table 1-2 (page 1-5)—Delete the large asterisk and the hand that points to the left, as well as the corresponding footnotes. We do not recommend different settings for Germany or the United Kingdom.

Table 1-3 (page 1-5)—Under Time Value, move the triangle to point to 150 seconds, to indicate that this is the manufacturer's recommended setting.

Figure 2-1 (page 2-2)—TIMER should be 150 SEC. Also DIP SW B should read 00101000.

Page 2-3—Time Value Setting is displayed on the screen as *TIMER 150 SEC*. 150 seconds is the default (recommended) setting. The setting can be changed to 120 seconds by resetting slide switch 3 on DIP Switch B to the *off* position.

Table 2-1 (page 2-4)—Delete the large asterisk and the hand that points to the left, as well as the corresponding footnotes. We do not recommend different settings for Germany or the United Kingdom.

Table 2-2 (page 2-4)—Under Time Value, move the triangle to point to 150 seconds, to indicate that this is the manufacturer's recommended setting.

For technical assistance, call your distributor or Atari Customer Service at (408) 434-3950 (Monday–Friday, 7:30 am–4:00 pm Pacific time)



Atari Games Corporation • 737 Sycamore Drive • P.O. Box 361110 • Milpitas, CA 95035