

Battle Cruiser M-12

Solder Side

GND	1	GND
GND	2	GND
-	3	-
Sp	4	Sp
+12V	5	+12V
Coin 1	6	Coin 2
-	7	-
-	8	Service
5V+	9	+5V
-	10	-
-	11	-
Coin Cont.	12	2Sp Start
Coin 1	13	1Sp "
1Sp Fever	14	1. rechts
Rot	15	1. links
2Sp rechts	16	Blau
2. links	17	Grün
2. Fever	18	Sync