

WIRING INSTRUCTION

FOR

"JUNGLE KING"

" CARINA "

PART SIDE			SOLDERING SIDE.
GND	1	1	GND
RED	2	2	GND
GREEN	3	3	BLUE
SYNC	4	4	-
SPUND(+)	5	5	SOUND(-)
-	6	6	-
-	7	7	-
-	8	8	-
-	9	9	-
-	10	10	-
COIN SW.	11	11	TILT SW.
1P. SELECT	12	12	2P. SELECT
1P. UP	13	13	2P. UP
1P. DOWN	14	14	2P. DOWN
1P. RIGHT	15	15	2P. RIGHT
1P. LEFT	16	16	2P. LEFT
-	17	17	-
-	18	18	-
-	19	19	-
-	20	20	-
1P. SHOOT & JUMP	21	21	2P. SHOOT & JUMP
-	22	22	-

1	2	3	4	5	6	7	8	9	10	11	12
GND				+5 V.			-	+12 V.	-	-	-